



## DAP-1350 Firmware Release Note

**Firmware:** v1.14 (EU)

**Hardware:** A1

**Date:** 29, May, 2012

### **Problems Resolved:**

1. Fix TSD0010382 and TSD0011014: Disable WPS-PIN Method issue.
2. Fix firmware upgrade issue when AP mode switches to Router mode.

### **Enhancements:**

1. N/A
-